Procedure to replace the voltage monitoring board.

- 1. LOTO the corresponding power supply. Location of the power supplies can be determined from BNL drawing XXXXX.
- 2. All measurements are performed under Class-A category, less than 50 volts.
- 3. Unplug the 45 volt (2 A) AC power supply that powers the voltage monitoring boards. The power supply is located in "B" alcove.
- 4. Unplug the 5 volt (500 mA) DC power supply that powers the 1-wire circuit on the voltage monitoring board.
- 5. Verify the leds on the voltage monitoring board are off.
- 6. Verify the voltage across the leads is zero volt.
- 7. Verify the voltage from the lead to ground is zero volt.
- 8. Disconnect all wires from the voltage monitoring board, replace the board and then reconnect all the wires.